Radioactive Sources



The RRS Radioactive Reference Sources feature:

- Traceable, certified 2 pi emission rates
- A safe and permanent container
- Accurate probe positioning for excellent repeatability.
- Hinged shutter for probe response checking at two count rates:
 i) shutter open rapid, accurate probe efficiency determination
 ii) shutter closed check at a nominal 10% of source emission rate.
- Colour-coded label indicating radionuclide and surface emission rate.
- Source active area matched to specific probe window area.

The CK-1 Check Source #9480008 is a "stay alive" button source used to check Survey Meter functionality.

Probe	Source	Nuclide	Emission Rate
<u>AP2/4A, AP2R, DP2/4A, DP2R/4A</u>	RRS 21A	²⁴¹ Am Alpha	2400/s
AP3/4A, AP3R/4A, DP3/4A, DP3R/4A	RRS 31A	²⁴¹ Am Alpha	2400/s
<u>AP5A</u> , <u>DP6A</u>	RRS 51A	²⁴¹ Am Alpha	111/s
<u>AP6A</u> , <u>DP8A</u>	RRH 11B	²⁴¹ Am Alpha	56/s
<u>BP4/4A,B,C</u>	RRS 12A	¹⁴ C Beta	4000/s
<u>BP7/4A</u>	RRS 22A	¹⁴ C Beta	4000/s
BP6/4A, BP6R/4A	RRS 32A	¹⁴ C Beta	4000/s
BP19AD	RRS 52A	¹⁴ C Beta	1110/s
BP4/4A,B,C	RRS 14A	³⁶ CI Beta	2150/s
BP7/4A, BP20/A, DP2/4A, DP2R/4A	RRS 24A	³⁶ CI Beta	2150/s
DP6AD, DP6BD, DP6CD, DP6DD, BP19AD	RRS 54A	³⁶ CI Beta	1110/s
BP13A	RRS 64A	³⁶ CI Beta	1110/s
BP17A, <u>DP8A</u>	RRH 14B	³⁶ CI Beta	550/s
GP13A	RRS 59A	¹²⁹ I Gamma	1110/s

